

ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್‌ರವರ ಕಛೇರಿ, ಉಪ ವಿಭಾಗ, ನಂಜನಗೂಡು.

ಸಂ:ಸಹಾಯ:ಲೋಇ:ಉವಿ:ಸಇಂ:ಸುಪ್ರಸ: 115 :2023-24

ದಿನಾಂಕ: 01-06-2023

ರವರಿಗೆ

ಕಾರ್ಯದರ್ಶಿ,
ಗ್ಲೋಬಲ್ ಪಬ್ಲಿಕ್ ಶಾಲೆ,
ನಂಜನಗೂಡು,
ಮೈಸೂರು ಜಿಲ್ಲೆ.

ಮಾನ್ಯರೇ,

ವಿಷಯ: ಗ್ಲೋಬಲ್ ಪಬ್ಲಿಕ್ ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡುವ ಬಗ್ಗೆ.

- ಉಲ್ಲೇಖ: 1. ಕಾರ್ಯದರ್ಶಿ, ಗ್ಲೋಬಲ್ ಪಬ್ಲಿಕ್ ಶಾಲೆ, ನಂಜನಗೂಡು ಇವರ ಪತ್ರ ದಿನಾಂಕ: 15.03.2022.
2. ಕರ್ನಾಟಕ ಸರ್ಕಾರದ ಸಚಿವಾಲಯ, ವಿಕಾಸ ಸೌಧ, ಬೆಂಗಳೂರು ರವರ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ ಲೋಇ 59 ಬಿಇಡಿ 2019 ದಿನಾಂಕ:06.05.2022.
3. ಕರ್ನಾಟಕ ಸರ್ಕಾರದ ಸಚಿವಾಲಯ, ವಿಕಾಸ ಸೌಧ, ಬೆಂಗಳೂರು ರವರ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ:ಇಡಿ 43 ಪಿಜಿಸಿ 2022, ದಿನಾಂಕ:18.05.2022.
4. ಈ ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ: 309-311/2022-23 ದಿನಾಂಕ: 07.07.2022

ಮೇಲಿನ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಉಲ್ಲೇಖ (1) ರಲ್ಲಿ ನೀವು ಮನವಿ ಪತ್ರ ಸಲ್ಲಿಸಿ, ತಮ್ಮ ಶಿಕ್ಷಣ ಸಂಸ್ಥೆಯ ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತೆಯ ಬಗ್ಗೆ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಬೇಕಾಗಿ ಕೋರಿದ್ದೀರಿ.

ಉಲ್ಲೇಖ (2) & (3) ರ ಸರ್ಕಾರದ ಆದೇಶದನ್ವಯ ಈ ಕೆಳಗೆ ತಿಳಿಸಿರುವಂತೆ ಪರೀಕ್ಷೆಯನ್ನು ನಡೆಸಿ ಉಲ್ಲೇಖ (4) ರಲ್ಲಿ ಕಟ್ಟಡದ ಸುರಕ್ಷಿತ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು 2022-23ನೇ ಸಾಲಿನ ಶೈಕ್ಷಣಿಕ ವರ್ಷಕ್ಕೆ ಅನ್ವಯವಾಗುವಂತೆ ನೀಡಲಾಗಿದೆ.

ಸದರಿ ಕಟ್ಟಡವನ್ನು ದಿನಾಂಕ:01.07.2022 ರಂದು ಪರಿಶೀಲಿಸಲಾಗಿ, ಕಟ್ಟಡವು ಸೆಲ, ಮೊದಲನೇ & ಎರಡನೇ ಮಹಡಿಗಳನ್ನು ಹೊಂದಿದ್ದು, 2018 ರಲ್ಲಿ ಪೂರ್ಣಗೊಂಡಿರುತ್ತದೆ. ಶ್ರೀ ಮಹಾರಾಜ ಇನ್ಸ್ಟಿಟ್ಯೂಟ್ ಆಫ್ ಟೆಕ್ನಾಲಜಿ ಮೈಸೂರು, ಬೆಳವಾಡಿ, ಶ್ರೀರಂಗಪಟ್ಟಣ ತಾಲ್ಲೂಕು, ಮಂಡ್ಯ ಕಾಲೇಜು ಇವರ ಉಸ್ತುವಾರಿಯಲ್ಲಿ ಪರಿಶೀಲಿಸಿದಂತೆ, ಸದರಿ ಕಟ್ಟಡದ ಸಿಲಿಂಗ್ ಎತ್ತರವು 3.00 ಮೀಟರ್ ಇರುವುದು ಕಂಡು ಬಂದಿರುತ್ತದೆ. ಹಾಗೂ ಮುಟ್ಟಿಲುಗಳನ್ನು NBC Code-2016 ರನ್ವಯ ನಿರ್ಮಿಸಲಾಗಿರುತ್ತದೆ. ಸದರಿ ಕಟ್ಟಡದಲ್ಲಿ ಶೌಚಾಲಯ ಮತ್ತು ಕುಡಿಯುವ ನೀರಿನ ವ್ಯವಸ್ಥೆ ಕಲ್ಪಿಸಲಾಗಿರುತ್ತದೆ.

ಮುಂದುವರೆದು, ಕಟ್ಟಡದ ಸುರಕ್ಷತೆಗೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಕಟ್ಟಡದ ಕಾಂಕ್ರೀಟ್ ಸದೃಢತೆಯ ಬಗ್ಗೆ ದಿನಾಂಕ:12.03.2022 ರಂದು ಶ್ರೀ ಮಹಾರಾಜ ಇನ್ಸ್ಟಿಟ್ಯೂಟ್ ಆಫ್ ಟೆಕ್ನಾಲಜಿ ಮೈಸೂರು, ಬೆಳವಾಡಿ, ಶ್ರೀರಂಗಪಟ್ಟಣ ತಾಲ್ಲೂಕು, ಮಂಡ್ಯ ಕಾಲೇಜಿನ ಸಿವಿಲ್ ಇಂಜಿನಿಯರಿಂಗ್ ವಿಭಾಗದ ಸಹಾಯಕ ಪ್ರಾಧ್ಯಾಪಕರು, **Non-destructive Digital indicating Tester** ಮುಖಾಂತರ ಹಾಗೂ **Physical observation & Accordingly necessary field Tests** ಪರೀಕ್ಷೆಗಳನ್ನು ಕೈಗೊಂಡು, ಸಮಾಲೋಚಕರೊಂದಿಗೆ ಉಪವಿಭಾಗದ ತಾಂತ್ರಿಕ ವರ್ಗವು ನಡೆಸಿರುವ ಪರೀಕ್ಷೆಯ ವರದಿಯಂತೆ ಕಟ್ಟಡವು ಸದೃಢತೆಯಿಂದ ಇರುವುದು ಕಂಡುಬಂದಿರುತ್ತದೆ.

- ಪಂಚಾಯತ್ ಅಭಿವೃದ್ಧಿ ಅಧಿಕಾರಿ, ದೇವೀರಮನಹಳ್ಳಿ ಪಂಚಾಯತಿ, ನಂಜನಗೂಡು ತಾಲ್ಲೂಕು ರವರು ಗ್ಲೋಬಲ್ ಪಬ್ಲಿಕ್ ಶಾಲಾ ಕಟ್ಟಡದ ನಿರೀಕ್ಷಣೆಗೆ ರವರಾದ ನೀಡಿರುತ್ತಾರೆ.
- ಮುಖ್ಯೋಪಾಧ್ಯಾಯರು, ಗ್ಲೋಬಲ್ ಪಬ್ಲಿಕ್ ಶಾಲೆ, ನಂಜನಗೂಡು, ಮೈಸೂರು ಜಿಲ್ಲೆರವರು ಸದರಿ ಸ್ಥಳದಲ್ಲಿ ಶಾಲಾ ಕಟ್ಟಡವನ್ನು ನಿರ್ಮಿಸಲಾಗಿರುವುದಾಗಿ ತಿಳಿಸಿರುತ್ತಾರೆ. ಅದರಂತೆ, ಕಟ್ಟಡವನ್ನು ಸದರಿ ಸ್ಥಳದಲ್ಲಿ ನಿರ್ಮಿಸಲಾಗಿರುತ್ತದೆ.

• **NDT Test**

Conducting Ultrasonic pulse velocity test for compressive strength of in-situ concrete on Columns, Beams and Slab using Portable ultrasonic non-destructive Digital indicating Tester ಉಪಕರಣದಲ್ಲಿ ಮತ್ತು Rebound Hammer ಪರೀಕ್ಷೆಯನ್ನು ಶ್ರೀ ಮಹಾರಾಜ ಇನ್ಸ್ಟಿಟ್ಯೂಟ್ ಆಫ್ ಟೆಕ್ನಾಲಜಿ ಮೈಸೂರು, ಬೆಳವಾಡಿ, ಶ್ರೀರಂಗಪಟ್ಟಣ ತಾಲ್ಲೂಕು, ಮಂಡ್ಯ ಕಾಲೇಜಿನ ಸಿವಿಲ್ ಇಂಜಿನಿಯರಿಂಗ್ ವಿಭಾಗದ

SECRETARY
GLOBAL PUBLIC SCHOOL
Devirammanahalli,
Near Vasuki Fuels,
Nanjangud Taluk


ಸಹಾಯಕ ಪ್ರಾಧ್ಯಾಪಕರು ಹಾಗೂ ಮುಖ್ಯಸ್ಥರವರಿಂದ ಕೈಗೊಳ್ಳಲಾಗಿರುತ್ತದೆ. ಸದರಿ ಪರೀಕ್ಷೆಯಲ್ಲಿ ಕಟ್ಟಡವು ಉತ್ತಮ ಗುಣಮಟ್ಟದಿಂದ ಕೂಡಿರುವುದು ಕಂಡುಬಂದಿರುತ್ತದೆ.

- Recognizance, visual inspection of Building-cracks, distress, dampness etc. ಪರೀಕ್ಷೆಯನ್ನು ಶ್ರೀ ಮಹಾರಾಜ ಇನ್ಸಿಟ್ಯೂಟ್ ಆಫ್ ಟೆಕ್ನಾಲಜಿ ಮೈಸೂರು, ಬೆಳವಾಡಿ, ಶ್ರೀರಂಗಪಟ್ಟಣ ತಾಲ್ಲೂಕು, ಮಂಡ್ಯ ಕಾಲೇಜಿನ ಸಿವಿಲ್ ಇಂಜಿನಿಯರಿಂಗ್ ವಿಭಾಗದ ಸಹಾಯಕ ಪ್ರಾಧ್ಯಾಪಕರು ಮತ್ತು ಮುಖ್ಯಸ್ಥರವರಿಂದ ಕೈಗೊಳ್ಳಲಾಗಿದ್ದು, ಪರೀಕ್ಷೆಯಲ್ಲಿ ಕಟ್ಟಡವು ಉತ್ತಮ ಗುಣಮಟ್ಟದಿಂದ ಕೂಡಿರುವುದು ಕಂಡುಬಂದಿರುತ್ತದೆ.
- National Building code of India 2016 ರ ಅನ್ವಯ Form for Certificate for Structural Stability ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನಾಗರಾಜ ಬಿ. ಕನ್ನಲ್ಲಿಂಗ್ ಡಿಸೈನ್ ಇಂಜಿನಿಯರ್, ಉದಯರವಿ ರಸ್ತೆ, ಕುವೆಂಪುನಗರ, ಮೈಸೂರು ರವರು ಮತ್ತು ಶಾಲಾ ಮುಖ್ಯಸ್ಥರು ವೃದ್ಧೀಕರಿಸಿರುತ್ತಾರೆ.
- ಉಲ್ಲೇಖ(2) & (3) ರ ಸರ್ಕಾರದ ಸುತ್ತೋಲೆಯಂತೆ ಕನಿಷ್ಠ ಎರಡು ರೀತಿಯ Non-destructive test ಗಳನ್ನು ಕೈಗೊಂಡು ಫಲಿತಾಂಶವನ್ನು ಪರಿಶೀಲಿಸಲು ಸೂಚಿಸಿರುವುದರಿಂದ ದಿನಾಂಕ:01.07.2022 ರಂದು ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆಯ ಗುಣ ಭರವಸೆ ಉಪವಿಭಾಗ ಮೈಸೂರು ರವರೊಂದಿಗೆ ಜಂಟಿಯಾಗಿ **Ultrasonic Pulse Velocity Test** ಮತ್ತು **Rebound Hammer test** ಗಳನ್ನು ಕೈಗೊಂಡು ಪರೀಕ್ಷಾ ವರದಿಯನ್ನು ಪಡೆಯಲಾಗಿದ್ದು, ಪರೀಕ್ಷೆಯಲ್ಲಿ ಕಟ್ಟಡವು ಉತ್ತಮ ಗುಣಮಟ್ಟದಿಂದ ಕೂಡಿರುವುದು ಕಂಡುಬಂದಿರುತ್ತದೆ.
- ಬ್ಯಾಂಕ್ ಆಫ್ ಬರೋಡಾ, ನಂಜನಗೂಡು ಶಾಖೆಯ ಡಿಡಿ ಸಂಖ್ಯೆ:102877, ದಿ:31.05.2023 ರಂದು ರೂ.5000/- ಗಳ ಡಿಡಿಯನ್ನು ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ಮೈಸೂರು ವಿಭಾಗ, ಮೈಸೂರು ರವರ ಹೆಸರಿಗೆ ಪಡೆದಿದ್ದು, ಸದರಿ ಡಿಡಿಯನ್ನು ಸಲ್ಲಿಸಿರುತ್ತಾರೆ.

ಸದರಿ ಸಂಸ್ಥೆಯವರು ನೀಡಿರುವ ಎಲ್ಲಾ ದಾಖಲೆಗಳನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ ಶ್ರೀ ಮಹಾರಾಜ ಇನ್ಸಿಟ್ಯೂಟ್ ಆಫ್ ಟೆಕ್ನಾಲಜಿ ಮೈಸೂರು, ಬೆಳವಾಡಿ, ಶ್ರೀರಂಗಪಟ್ಟಣ ತಾಲ್ಲೂಕು, ಮಂಡ್ಯ ಕಾಲೇಜಿನ ಸಿವಿಲ್ ಇಂಜಿನಿಯರಿಂಗ್ ವಿಭಾಗದ ಸಹಾಯಕ ಪ್ರಾಧ್ಯಾಪಕರು ಮತ್ತು ಮುಖ್ಯಸ್ಥರು ರವರು ನೀಡಿರುವ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಪರಿಗಣಿಸಿ ಕಟ್ಟಡವು ರಚನಾತ್ಮಕವಾಗಿ ಸುರಕ್ಷಿತವಾಗಿದೆಯೆಂದು ಹಾಗೂ ಕಟ್ಟಡವನ್ನು ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆಯ ಶಾಂತಿಕ ತಂಡ ಪರಿಶೀಲಿಸಲಾಗಿ, ಕಟ್ಟಡವು "Structurally Stable" ಇರುವುದಾಗಿ ಪರೀಕ್ಷಾ ವರದಿಗಳಿಂದ ಕಂಡುಬಂದಿರುವುದರಿಂದ ಸದರಿ ಕಟ್ಟಡವು "Structurally Stable" ಇದೆ ಎಂದು ಪ್ರಸಕ್ತ ಶೈಕ್ಷಣಿಕ ಸಾಲಿಗೆ ಕಟ್ಟಡ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ
ಉಪ ವಿಭಾಗ, ನಂಜನಗೂಡು.


SECRETARY
GLOBAL PUBLIC SCHOOL
Devirammanahalli,
Near Vasuki Fuels,
Nanjangud Taluk

SECRETARY
GLOBAL PUBLIC SCHOOL
Devirammanahalli,
Near Vasuki Fuels,
Nanjangud Taluk

**GOVERNMENT OF KARNATAKA
PUBLIC WORKS DEPARTMENT
OFFICE OF THE ASSISTANT EXECUTIVE ENGINEER
NANJANGUD SUB DIVISION**

No.AEE:PWD:SD:SP115:2023-24

Date: 01/06/2023

To

Secretary,
Global Public School,
Nanjangud,
Mysuru District.

Sir,

Sub: Issue of safety certificate to the Global
Public School building.

- Ref: 1. Letter dated 15/03/2022 of the Secretary of the Secretary,
Global Public school, Nanjangud.
2. Circular No.PWD59BED 2019 dated 06/05/2022 issued by the
Karnataka Government Secretariat, Vidhana Soudha,
Bangalore.
3. Circular No.ED43PGC 2022 dated 18/05/2022 issued by the
Karnataka Government Secretariat, Vidhana Soudha,
Bangalore.
4. Letter No.309-311/2022-23 dated 07/07/2022 of this office.


With reference to the above, vide reference cited at reference (1) above you have sent a requisition letter praying for issue of safety certificate for your school building.

That after conducting tests in accordance with the Government Circulars cited at reference (2) & (3) above, building safety certificate for the academic year 2022-23 has been granted.

The said building was inspected on 01/07/2022, the building is having ground, first and second floor and has been completed in the year 2018. As per the inspection conducted in the presence of Sri Maharaja Institute of Technology, Mysuru, Belavadi, Srirangapatna taluk, Mandya college, it appears that the height of the ceiling of the building is 3 mtr and the staircase steps have been constructed as per the NBC code-2016 and the building is provided with toilet and drinking water facility.

10 of Corrections. *red*

Ad
**SECRETARY
GLOBAL PUBLIC SCHOOL
Devirammanahalli,
Near Vasuki Fuels,
Nanjangud Taluk**



Further, regarding the safety of the building, testing of the quality of the concrete has been conducted in the presence of Assistant Professor, Civil Engineering department, Institute of Sri Maharaja Institute of Technology, Mysuru, Belavadi, Srirangapatna taluk, Mandya college by using non-destructive digital indicating tester and physical observation and accordingly necessary field tests have been conducted and according to the test conducted by them, the building is in good condition.

The Panchayath Development Officer, Devirammanahalli panchayath, Nanjangud taluk has issued license for construction of the building of Global Public School.

The Head master, Global Public school, Mysuru district have informed that the said school is constructed in the said premises.

NDT test,

- Ultrasonic pulse velocity test for comprehensive strength of in-situ concrete on Columns, Beams and Slab using portable ultrasonic non-destructive digital indicating tester instrument and rebound hammer has been conducted by the Assistant Professor and Head of Sri Maharaja Institute of Technology, Mysuru, Belavadi, Srirangapatna taluk, Mandya college.
- Recognizance visual inspection of building-cracks, distress, jampness etc test has been conducted by the Head of Sri Maharaja Institute of Technology, Mysuru, Belavadi, Srirangapatna taluk, Mandya and the building is found qualitative.
- Nagaraja B., Consulting Design Engineer, Udayaravi road, Kuvempunagar, Mysuru has issued form for certificate for structural stability and the same has been certified by the Head of the school.
- As per Government Circular cited at reference (2) & (3) above test for having conducted ultrasonic pulse velocity test and rebound hammer test jointly with the quality assurance department of PWD sub division, Mysuru and the report has been received. It is found that the building is having good standard.
- DD bearing No.102877 dated 31/05/2023 for Rs.5,000/- drawn on Bank of Baroda, Nanjangud branch in the name of Executive Engineer, PWD department, Mysuru division, Mysuru has also been submitted.
- After careful examination of all the documents produced by the said institution and considering the certificate issued by the Assistant Professor and Head of the Department of Sri Maharaja Institute.

No of Corrections. *Red*




Abu
SECRETARY
GLOBAL PUBLIC SCHOOL
 Devirammanahalli,
 Near Vasuki Fuels,
 Nanjangud Taluk

- That the building is structurally stable. Accordingly, since the building is structurally stable, building safety certificate for the current academic year is hereby granted.

Yours faithfully,

Assistant Executive Engineer,
Nanjangud Sub Division,
PW Department.

No of Corrections *red*



EXECUTION ADMITTED
BEFORE ME

H.N. Malleshiah
Notary, Mysore District, Karnataka

30/6/2023

Abh

SECRETARY
GLOBAL PUBLIC SCHOOL
Devirammanahalli,
Near Vasuki Fuels,
Nanjangud Taluk

With reference to the above letter, you are requested to issue a building safety certificate for your school building.

The building was inspected on 01/07/2023. The building is having ground, first and second floor and has been completed in the year 2018. As per the inspection conducted in the presence of Sr. Mahadeva Institute of Technology, Mysuru, Belavadi, Srirangapatna Taluk, Mandya District, it appears that the height of the ceiling of the building is 3m and the staircase steps have been constructed as per the NBC code 2016. The building is provided with underground drinking water facility.

No of Corrections *red*

SECRETARY
GLOBAL PUBLIC SCHOOL
Devirammanahalli,
Near Vasuki Fuels,
Nanjangud Taluk



ಕರ್ನಾಟಕ ಸರ್ಕಾರ



ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್‌ರವರ ಕಛೇರಿ, ಉಪ ವಿಭಾಗ, ನಂಜನಗೂಡು.

Date: 13/12/2023

ಸಂ:ಸಕಾಇಂ:ಲೋಇ:ಉವಿ:ಸಇಂ:731:2023-24

ದಿನಾಂಕ: 13-12-23

ರವರಿಗೆ

ಕಾರ್ಯದರ್ಶಿ

ಗ್ಲೋಬಲ್ ಪಬ್ಲಿಕ್ ಶಾಲೆ,

ನಂಜನಗೂಡು,

ಮೈಸೂರು ಜಿಲ್ಲೆ.

ಮಾನ್ಯರೇ,

ವಿಷಯ: ಗ್ಲೋಬಲ್ ಪಬ್ಲಿಕ್ ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಸಿಬಿಎಸ್‌ಇ ಬೋರ್ಡ್ ನೀಡಿರುವ ಅನುಬಂಧದ ಅನುಸಾರ ನೀಡುವ ಬಗ್ಗೆ.

- ಉಲ್ಲೇಖ: 1. ಮುಖ್ಯೋಪಾಧ್ಯಾಯರು, ಗ್ಲೋಬಲ್ ಪಬ್ಲಿಕ್ ಶಾಲೆ, ನಂಜನಗೂಡು ಇವರ ಪತ್ರ ದಿನಾಂಕ: 12-12-2023
2. ಈ ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ: ಸಕಾಇಂ:ಲೋಇ:ಉವಿ:ಸಇಂ:ಸುಪ್ರಪ:115:2022-23 ದಿನಾಂಕ: 01-06-2023

ಮೇಲಿನ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಉಲ್ಲೇಖಿತ ಪತ್ರ (1) ರಲ್ಲಿ ನೀವು ಮನವಿ ಪತ್ರ ಸಲ್ಲಿಸಿ, ತಮ್ಮ ಶಿಕ್ಷಣ ಸಂಸ್ಥೆಯ ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತೆಯ ಬಗ್ಗೆ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಸಿಬಿಎಸ್‌ಇ ಬೋರ್ಡ್ ನೀಡಿರುವ ಅನುಬಂಧದ ಅನುಸಾರ ನೀಡಬೇಕಾಗಿ ಕೋರಿರುತ್ತೀರಿ. ಉಲ್ಲೇಖಿತ ಪತ್ರ (2) ರಲ್ಲಿ ಪ್ರಸಕ್ತ ಶೈಕ್ಷಣಿಕ ಸಾಲಿಗೆ ಕಟ್ಟಡ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಿದ್ದು, ಅದರಂತೆ ತಾವು ಕೋರಿರುವ ಶಾಲಾ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಸಿಬಿಎಸ್‌ಇ ಬೋರ್ಡ್ ನೀಡಿರುವ ಅನುಬಂಧದ ಅನುಸಾರ ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,


13/12/2023

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್


ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ಉಪ ವಿಭಾಗ, ನಂಜನಗೂಡು.


13/12/2023

Nanjangod, Mysore

SECRETARY
GLOBAL PUBLIC SCHOOL
Devirammanahalli, Near Vasuki Fuels,
Nanjangod Taluk


SECRETARY
GLOBAL PUBLIC SCHOOL
Devirammanahalli, Near Vasuki Fuels,
Nanjangod Taluk

BUILDING SAFETY CERTIFICATE

No.

Dated: 13/12/2023

Certified that the existing building GLOBAL PUBLIC SCHOOL, at Devirammanahalli, Near Vasuki Fuels, Nanjangud comprised of two (upper floors) owned/occupied by GLOBAL PUBLIC SCHOOL have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Department of Public Works on 01/07/2022 in the presence of Mrs. Chethana N, Headmistress, Global Public School, Devirammanahalli, Near Vasuki Fuels, Nanjangud and that the building/premises is fit for occupancy upto classes X with effect from 01/06/2023 for a period of one year.

Global Public School had requested for Building Safety Certificate as per CBSE norms. So we have inspected the school and issued the Certificate on 13/12/2023 at Department of Public Works, Assistant Executive Engineer Office, Sub Division Nanjangud by

Signature Sathyanarayana 13/12/2023
Office of the Assistant Executive Engineer
P.W.P Sub-Division,
Nanjangud

Name : SATHYANARAYANA BJ

Designation : Assistant executive engineer

Name & Address of Department/ Office: _

OFFICE OF ASSISTANT EXECUTIVE
ENGINEER, PWD sub division
Nanjangud. Mysore.


SECRETARY
GLOBAL PUBLIC SCHOOL
Devirammanahalli, Near Vasuki Fuels,
Nanjangud Taluk

SECRETARY
GLOBAL PUBLIC SCHOOL
Devirammanahalli, Near Vasuki Fuels,
Nanjangud Taluk

**GOVERNMENT OF KARNATAKA
PUBLIC WORKS DEPARTMENT
OFFICE OF THE ASSISTANT EXECUTIVE ENGINEER
NANJANGUD SUB DIVISION**

No.AEE:PWD:SD:SP 731:2023-24

Date: 13/12/2023

To

Secretary,
Global Public School,
Nanjangud,
Mysuru District.

Sir,

Sub: Issue of safety certificate to the Global Public school building as per CBSE board Annexure.


- Ref: 1. Letter dated 12/12/2023 of the Headmistress, Global Public school, Nanjangud.
2. Letter No.AEE:PWD:SD:SP 115:2022-23 dated 01/06/2023 of this office.

With reference to the above, vide reference cited at reference (1) above you have sent a requisition letter for issue of safety certificate for your school building as per the CBSE board circular Annexure. That after cited at reference (2) above, building safety certificate for the current academic year 2023-24 has been granted, and according to the request from school, Building Safety Certificate is been granted as per the CBSE board Circular Annexure.

Sd/-

Assistant Executive Engineer,
Nanjangud Sub Division,
PW Department.

Ali
**SECRETARY
GLOBAL PUBLIC SCHOOL
Devirammanahalli, Near Vasuki Fuels,
Nanjangud T. uk**



I.N. MALLESHAPATI 13/12/2023
**I.N. MALLESHAPATI, B.A., LL.B.,
ADVOCATE & NOTARY
No. 5, Sri Lakshmi Complex
Coty Main Road, NANJANGUD-571 309**